

DANGER AND CAUTION STICKER PLACEMENT ON MANLIFT

Danger Sticker Placement:

One 2.5 x 6" Danger Sticker should be placed on the 3" channel guide rail on the "up" travel side of the manlift facing so that the rider can see it when approaching the manlift. This should be done at all landings on the "up" travel side of the manlift.

One 1 x 6" Danger Sticker should be placed on the 1 3/8" channel guide rail on the "up" travel side of the manlift facing so that the rider can see it when stepping on to the manlift step. This should be done at all landings on the "up" travel side of the manlift.

One 2.5 x 6" Danger Sticker should be placed on the 3" channel guide rail on the "down" travel side of the manlift. This should be done at all landings on the "down" travel side of the manlift.

One 1 x 6" Danger Sticker should be placed on the 1 3/8" channel guide rail on the "down" travel side of the manlift facing so that the rider can see it when stepping off the manlift step. This should be done at all landings on the "down" travel side of the manlift.

Caution: Pinch Point Sticker Placement:

One 2.6 x 6" Caution Sticker should be placed on the 3" guide rail near both the head and foot pulleys on both sides of the manlift.

One 1 x 6" Caution Sticker should be placed should be placed on the 1 3/8" channel guide rail near both the head and foot pulleys on both sides of the manlift.